

The FLUKE logo is displayed in a bold, black, sans-serif font on a yellow rectangular background.

Calibration

Temperature Calibration

Tips and tricks from the real world

Bouraoui KHACHLOUF

*Technical Sales Manager
Temperature & Humidity EMEA*



Agenda

FLUKE®

Calibration


Few tips and tricks you can use to keep things up and running:

- How to get the best calibration results
- System Calibration & sensor Calibration
- How to protect your calibration investments
- How to minimize the number of tools you take onsite
- How to do more in less time
- Automate Temperature Calibration without Software
- Questions & Answers




Fixed Point vs. Comparison Calibrations

Two kinds of Calibration



Comparison Calibration





Fixed Point Calibration

Temperature measurement devices


FLUKE®

Calibration

- Liquid-in-glass/Dial thermometer - Thermal expansion
the property measured is the length of the liquid column inside a glass tube or metal expansion
- Platinum resistance thermometer or a thermistor - the property measured is the electrical resistance of a piece of 'sensing' material
- Thermocouple - the property measured is the voltage generated along the wires making up the thermocouple




What is temperature ?



- The temperature of an object is a measure of the energy of the molecules in that object
- Industrial processes require a knowledge of temperature
- We measure temperature with sensors such as thermocouples and RTDs sometimes incorporated into transmitters
- What do we need to ensure these devices are reading correctly ?


Zeroth law of thermodynamics

Thermodynamic equilibrium



Zeroth law of thermodynamics

Thermodynamic equilibrium



How do we measure temperature ?

Indirectly - with a thermometer

A thermometer is a device which has a measurable property which changes with temperature

Tip #1 The truth about calibrating temperature sensors

- You cannot calibrate a temperature sensor if you wanted to, because a sensor cannot be physically adjusted
- yes you can. There are two ways to do it. You can calibrate the sensors as part of a system, or you can calibrate the sensors individually



**Thermometer readout:
Super-DAQ with DAQ-
STAQ Multiplexer**



**Reference
standard: PRT**



**Temperature
source: Bath**



Tip #1 The truth about calibrating temperature sensors



• System Calibration definition

It is a calibration where:

- The readout and probe are connected as normally used
- A reference thermometer is used to verify nominal temperatures
- For an accredited calibration, the reference thermometer is also the “transfer” standard for traceability purposes
- A “Report of Calibration” summarizes the received condition (or “As-Found” state), any changes to the system, the Completed Condition (or “As-Left” state), and documentation of traceability
- The same nominal temperatures are used for both “As-Found” and “As-Left” data.

System Calibration process steps



1. Reference thermometer check
2. Record "As-Found" data
3. Evaluate "As-Found" data
4. Determine next step (anneal, align, or reject)
5. Anneal (if required)
6. Generate new coefficients (if data is good)
7. Program new coefficients into UUT readout
8. Record "As-Left" data
9. Evaluate results vs. limits
10. Build "Report of Calibration"

Reference thermometer check

FLUKE®

Calibration

Always check your reference, before you start your calibration



Data collection tips



- Start with an “As-Found” 0 °C point
- Measure the above 0 °C temperatures first
- Take a 0 °C “mid” point
- Then take the below 0 °C temperatures
- Finally, take the 0 °C “As-Left” point.

Taking multiple 0 °C points helps determine repeatability and stability of your probes

System As Found:
 Test Equipment Used: 1595A-XXXXXX / 5699-XXXX
 Model: 1502A
 Rtpw: 99.9399
 Serial: XXXXXX
 A High: -4.910578 E-04
 A Low: -5.425354 E-04
 B High: -1.414533 E-04
 B Low: 5.042130 E-05

Channel: _1_ Model: 565-6 Serial: XXXXXX

	Nominal °C	Actual °C	UUT °C	UUT Ω	UUT s °C	Max / Min °C	Max / Min Ω	Tol.	Pass / Fail
Cold points	0 ASL	0.0160	-0.067	99.9088					
	-197.000	-196.9031	-196.904	18.3501					
	-38.831	-38.8181	-38.914	84.3398					
	0 MID	0.0162	-0.066	99.9096		-0.067 .066	9096 .9089		
Hot points	231.928	231.9188	231.798	189.0450		.750 .797	.0451 .0449		
	300.000	299.9928	299.797	214.0081		.798 .797	.0082 .0081		
	0 ASF	0.0158	-0.069	99.9163					



Generate new coefficients using Tableware

FLUKE®

Calibration

So the data looks good...

- Time to perform the alignment!
 - I use Tableware, from Fluke when doing manual calculations.
 - Select the “P/T” button in Tableware.
 - Enter the Probe model & Serial information.





Generating new coefficients cont.

FLUKE®

Calibration

- Select the range of the calibration (by sub-range)
- And start entering the data
 - ❖ Always select “°C” and “Ohms”
 - ❖ Use the average of your 0 °C points



Generating new coefficients cont.

FLUKE®

Calibration

- Enter in the Below 0 °C data
- And the Above 0 °C data
- And click “Calculate”

Raw Data

Enter Raw Data for ITS-90 Coefficients:

Reference Scale: °C K °F

UUT Scale: Ohms KOhms

T.P. of Water **Low Range** High Range

Reference Temperatures:	UUT Resistances:
-196.9034	18.3501
-38.8481	84.

Step 1: Select the Reference and UUT scales.

Step 2: Fill in the required Yellow fields.

Step 3: The White fields may optionally be filled in.

Calculate

Cancel

Help

Raw Data

Enter Raw Data for ITS-90 Coefficients:

Reference Scale: °C K °F

UUT Scale: Ohms KOhms

T.P. of Water Low Range **High Range**

Reference Temperatures:	UUT Resistances:
231.9188	189.0450
299.9928	214.0081

Step 1: Select the Reference and UUT scales.

Step 2: Fill in the required Yellow fields.

Step 3: The White fields may optionally be filled in.

Calculate

Cancel

Help

Generating new coefficients cont.

FLUKE®

Calibration

- Here are the new probe coefficients!

Coefficients and Residuals

Results of Coefficient Calculations:

These are the results of the coefficient calculations for Model: 5615-6
Serial: XXXXXX:

Coefficients:	Set-points and Residuals:
RTPw = 99.909210	Low Range:
a[4] = -4.76359835 E-04	-196.9034°C 0.0000°C
b[4] = 1.28267488 E-04	-38.8481°C 0.0001°C
a[8] = -5.86472406 E-04	High Range:
b[8] = -9.09382243 E-05	231.9188°C 0.0001°C
	299.9928°C 0.0001°C

Export

Print Report

Table Options

Back

Close

Help

Program the readout

FLUKE®

Calibration

- Press the “Menu” button on the 1502A.
- Press the “Probe” button when you see “SETP”. The readout will display the Coefficient Type (t90= ITS-90, rtd= CVD, t68= IPTS-68)
- Press the “Enter” key (same as “Menu” key).



Program the readout cont.

FLUKE®

Calibration

- “r0.01” should appear temporarily, then advance to the RTPW entry
- Use the green up/down arrows to change the value of each digit, and the left/right arrows to advance to the next position.
- After you set the “RTPW” value by pressing enter, it will advance you to the “a” (“A positive”), to allow you to input the “A” Coefficient value.



Program the readout cont.

FLUKE®

Calibration

- After each coefficient is entered, the readout will display “E” to enter the exponent.
- To change exponents, use the “UP” key to increase, and the “DOWN” key to reduce the exponent. You will do this for each coefficient you have, “b”, “c”, “d”, “a4”, “b4” etc.



Tip #1 The truth about calibrating temperature sensors

- In the second method the temperature sensors are calibrated separate from the electronics and receive a calibration report with corrections that are later entered into the electronics connected temperature sensor for an accurate temperature reading

Report Number:
B1202017

**Fluke Calibration, American Fork
Primary Temperature Lab
Report of Calibration**

Page 2 of 8

The PRT was calibrated at the following temperatures with the associated uncertainties. The uncertainty evaluation accounts for all known uncertainties present at the time of calibration including long-term behavior of the calibration system, measurement noise, and any short-term effects of the PRT. The uncertainties are reported at the calibration temperatures only. The uncertainties at intermediate temperatures can be computed from these values and the ITS-90 propagation of error curves. The uncertainties are reported at a coverage factor of 2 (k=2).

CALIBRATION POINT			TEMPERATURE	MEASURED	UNCERTAINTY	
(point °C)	(type)	(SN)	t90(°C)	RESISTANCE	(mK)	
-197.000	Comp	N/A	-197.000	18.2097	±6.0	
-100.000	Comp	N/A	-100.000	59.2614	±10.0	
-38.834	Comp	N/A	-38.834	84.1391	±6.0	
0.010	Comp	N/A	0.010	99.6745	±4.0	
	In	FP	44013	156.599	160.4537	±6.0
	Sn	FP	S7005	231.928	188.6586	±6.0
	Zn	FP	S9007	419.527	256.0466	±9.0
	Al	FP	47007	660.323	336.4755	±14.0


The following values were determined for the RTPW and the coefficients of the pertinent deviation functions of the ITS-90. For best results, the RTPW value shown should be used as a baseline value for determining the stability of the PRT. The user should maintain a record of RTPW values measured as a routine operation and use these values when computing temperature.

Results for Nominal Current Calibration

RTPW = 99.6745 Ω

a4 = -1.320865 E-05
b4 = -2.063356 E-06
a7 = -8.464574 E-05
b7 = 7.092116 E-05
c7 = -3.463376 E-05

Defining Temperatures of the ITS-90



Fixed Point Calibration - Equipment Needed

FLUKE®

Calibration

Reference Standard

Fixed Point Cells

- triple point of water, mercury, indium, tin, zinc, aluminum, silver, copper, gallium



5901 Triple Point of Water Cells



59XX ITS-90 Fixed Point Cells



59XX Mini Fixed Point Cells

Temperature Source

Maintenance Bath, Furnace

- a device to maintain the temperature of the cell



7312 TPW Maintenance Bath



9116A Metrology Furnace



9260 Mini Fixed Point Furnace

Thermometer Readout

Super Thermometer

- a device to read the SPRT under test



1595A Super Thermometer

Fixed Point Calibration Example

FLUKE®


Calibration

**Thermometer readout:
1595A Super-Thermometer**



**Reference
standard:
Fixed point cell**

**Temperature source:
9116A Furnace**



Tip #2 Calibration baths usually deliver the best results



1- Calibration baths provide a very stable and uniform temperature environment. Stability refers to temperatures remaining constant over time and uniformity refers to the sameness of temperature vertically and horizontally all around the working region of the calibration bath

2- Owing to the exceptional stability and uniformity of a calibration bath, they provide the lowest uncertainties possible for comparison calibrations.

3. Calibration baths are compatible with the widest variety of temperature probes. They can accommodate many shapes and sizes and provide sufficient immersion to assure that both the temperature probes and the temperature standard are at the same temperature.

4. Calibration baths are an excellent choice for calibration of many temperature probes in one batch due to the large access openings.




Tip #3 Calibrate more workload with a calibration bath

The great thing about a calibration bath is that the working area can be large enough to calibrate several probes at a time (our laboratory usually calibrates 10 at a time), and the probes can have a range of shapes and sizes. So if your customers or coworkers may bring you anything under the sun to calibrate then you definitely want a calibration bath. But, what if you still need to calibrate all of those different kinds of probes onsite? Use a Micro-Bath. They are easily carried in one hand, but still have many calibration bath advantages.



Liquid & Glass Requirements




- **Designed for Stability (not necessarily speed)**
- **Secondary calibration lab typical application**
- **Temperature range limited to range of fluid used**
- **Large volumes and odd shaped or large diameter probes**
- **Different types of heat and cool/stirring**

The 2019-DCB Liquid-in-Glass Thermometer Calibration Kit includes a carousel which holds up to 10 thermometers and an adapter tube which raises the bath fluid level to within 5–15 mm of the thermometers' readings. The 2069 Magnifier Scope mounts easily to the front of any Deep-Well Compact Bath to provide magnification of 8X or greater

Liquid Baths

FLUKE®

Calibration



Tip #3 Boost productivity with multiple calibration baths

- One reason a temperature calibration bath is so stable is the bath fluid prevents the temperature from changing rapidly.
- This has unwanted side effect of slowing the rate baths change to the next temperature test point. One way to boost productivity is to use more than one bath so that you always are ready for the next cardinal temperature



Tip #4 Protect your investment with a triple point of water cell

FLUKE®

Calibration

- If you have invested in an SPRT or a secondary reference thermometer for better accuracy, the last thing you want is to lose all of that accuracy because of an accident that you don't even know about. Accidents can happen when you least expect them to and they can often happen in shipping before you ever take possession of your thermometer. The best way to be sure that your investment is protected is by checking it regularly in a triple point of water cell and comparing the result to your calibration report. The best practice is to keep a chart on the thermometer in a spreadsheet like Excel and watch for any sudden jumps in the reading at the triple point of water ($0.010\text{ }^{\circ}\text{C}$).




Control Chart of Reference Probes

Measure temperature using resistance ratio $W(t)$

$$W(t) = R(t) / R_{tpw}$$


$W(t)$ is much more stable over time than resistance only.

Regularly updating R_{tpw} greatly improves calibration uncertainty and lowers risk of erroneous measurements




- Thin-film

- Thin platinum foil mounted or deposited to a ceramic substrate and encapsulated inside a metal sheath
- Very rugged, poor repeatability



- Wire-wound

- Sensor wire is wound into a small-diameter coil which is mounted to a support . Support is filled with insulating alumina powder. Sensor is mounted inside a SST sheath
- More accurate, good repeatability, can be delicate



PRT characteristics

1. Wide temperature range
2. Best accuracy over full range – linear
3. Nominal resistance typically 100 Ω or 25 Ω at 0 $^{\circ}\text{C}$
4. Wide applicability
5. Can be more expensive than other thermometers but generally most “bang for the buck” ROI
6. Susceptible to drift
7. Range from industrial sensors to highly accurate reference level devices (SPRT – Standard Platinum Resistance Thermometer)

Understanding PRT drift

- What is drift?
 - Drift is a change in the probes resistance that causes measurement error
 - All PRTs drift due, some a little, others a lot
- Two main causes of drift
 - Mechanical strain
 - Oxidation
- Other sources of drift
 - Moisture leaking into the probe
 - Loss of fill gas (inert gas mixture as noble gases like argon, helium, or nitrogen)
 - Aging of materials
 - Contamination of the platinum sensor

Understanding mechanical strain


- Mechanical strain is caused by vibration or mechanical shock
 - Dropping
 - Tapping
 - Mishandling in shipping
- Introduces deformations in the resistance element resulting in increased resistance
 - Changes can be as large as 0.1 °C
 - Small effects are reversible through annealing
 - Catastrophic strain cannot be remedied

Examples of irreversible strain

FLUKE®


Calibration

- Magnified images of severely damaged platinum sensing elements



Another source of strain



- Cold quenching / thermal shock
 - Caused by rapid cooling of a hot ($> 500\text{ }^{\circ}\text{C}$) thermometer
 - Introduces crystal lattice vacancies with resulting increases in resistance
 - Most effects are reversible by annealing
 - Some probes are designed to be rapidly cooled, others are very sensitive to it



Understanding oxidation

- Caused by a chemical reaction with oxygen
- Introduces deviations in the chemical composition of the sensor
- As the sensor wire oxidizes the wire diameter is reduced causing an increase in resistance
- Some oxidation is needed to protect the sensor
- Changes generally do not exceed 0.005 °C
- Most effects are reversible by annealing
- Maximized at temperatures between 100 and 450 °C


Cross section of oxidation free platinum wire



Platinum wire with layer of oxidation reduces wire diameter

How to identify drift

- PRTs are specified for stability (short term repeatability and long term drift)
 - Drift is affected by time and use
 - Drift must be verified
- Monitor drift using interim checks
 - Periodically check at a known temperature
 - Use a repeatable temperature point such as triple-point of water or ice bath
 - Record results in a control chart
 - Assign drift limit



Anneal to reverse drift

- Annealing is the action of heating the sensor to a point that softens the platinum wire to allow realignment of crystalline structure (above 450 °C)
- High temperatures (above 450 °C) can also drive oxidation from the sensor
- Sensor must be of strain-free design for most effective annealing
 - SPRTs and high quality PRTs are designed with strain-free or partially strain-free sensors
 - Industrial PRTs have supported sensors that will deform at annealing temperatures which causes hysteresis

Annealing recommendations

FLUKE®

Calibration

- Always consult manufacturer for annealing guidelines
- Don't exceed maximum temperature of the probe
- Avoid using metal block furnaces when annealing quartz-sheathed SPRTs above 500 °C
 - Metal ions can pass through quartz and adhere to the sensor
- Incorrect annealing can irreversibly damage a probe
- Exceeding annealing temperature of probe calibration can cause calibration invalidation



Guidelines for annealing PRTs

- For high temperature PRTs (range up to 660 °C), anneal temperature is typically 665 °C.
- For other PRTs, some annealing can be achieved from about 300 °C and up.
- Many types of high quality PRTs are partially supported
 - Can't be fully annealed due to support
 - “Heat Treating” is used to stabilize the probe before calibration
 - Expose the probe to max cal temperature +10 °C for stabilization before calibration

Steps for annealing PRTs


FLUKE®

Calibration

- For high temperature PRTs
 1. Measure resistance at triple-point of water
 2. Anneal at 665 °C for 4 hours
 3. Ramp down to 480 °C at ramp rate of 2 °C per minute
 4. Remove probe to ambient
 5. Measure resistance at triple-point of water
 6. Calculate change in resistance
 7. Repeat if necessary
- For other PRTs
 1. Measure R_{TPW}
 2. Heat treat at highest calibration point +10 °C
 3. Measure R_{TPW}
 4. Repeat if necessary

Guidelines for annealing SPRTs

- You must know the allowed annealing temperature of the SPRT!
 - Some SPRTs have materials that will break down above 500 °C
- When annealing at high temperatures (665 °C), ramp furnace down to 480 °C before removing to ambient
- Don't ramp down to ambient (will cause oxidation)
- Make sure sheaths are cleaned before annealing
 - Contamination will cause glass sheaths to break down (devitrify) at high temperatures



Steps for annealing SPRTs

FLUKE®

Calibration

- Regular SPRT annealing process:
 1. Measure R_{TPW}
 2. Anneal at 480 °C for 4 hours
 3. Remove to ambient
 4. Measure R_{TPW}
 5. Repeat until resistance doesn't change (changes less than 0.4 mK)

High temperature SPRT annealing


FLUKE®

Calibration

- High temperature SPRT annealing process (SPRTs used up to 660 °C):
 1. Measure R_{TPW}
 2. Insert probe in furnace at 480 °C
 3. Soak at 480 °C for 4 hours
 4. Ramp furnace to 665 °C at 2 °C/minute
 5. Soak at 665 °C for 2 hours
 6. Ramp down to 480 °C at 2 °C/minute
 7. Remove to ambient
 8. Measure R_{TPW}
 9. Repeat until resistance doesn't change (changes less than 0.4 mK)
- For ultra-high temperature SPRT annealing (SPRTs up to 965 °C), consult with the manufacturer

Tip #5 Minimize the number of tools you take onsite

- If you perform onsite calibrations, time and space are a premium and the last thing you need is to spend most of your time hauling equipment around. Try to use the fewest instruments necessary for the job.
- For example, the process version of the Field Metrology Well is a dry-block calibrator that has all of the electronics you need built right in for measuring RTDs, thermocouples, and thermal switches. It is also a documenting 4-20 mA loop calibrator.
- You won't need a computer to automate and document the calibration either. It's built right in!




Tip #6 Infrared temperature calibration needs infrared temperature standards

- Infrared temperature readings are influenced greatly by the type material and surface finish of the objects they are pointed at, because infrared temperature readings depend on surface emissivity. Infrared calibrators are sometimes called blackbody calibrators even though a flat painted surface is not really a blackbody. Real blackbodies are cavities with a well-known emissivity value (i.e. 1.000 ± 0.001)
- The emissivity of a painted surface is only known if it is measured. Therefore, to calibrate an infrared thermometer you will need to use an infrared temperature standard like a radiometer or you will need a radiometrically calibrated calibrator. Most infrared calibrators are temperature sources like the 9132 and 9133 that require an infrared temperature standard to compare to the infrared thermometers being tested. However the 4180 Series Precision Infrared Calibrators have been radiometrically calibrated in our infrared thermometry laboratory with some of the lowest uncertainties possible so that expensive extra equipment is not required.



Tip #7 Boost calibrator accuracy with a platinum resistance thermometer (PRT)

- The convenience of a handheld dry-well is very appealing but sometimes you need a little more accuracy. A great way to improve the accuracy of any dry-well is to use a platinum resistance temperature standard for your known temperature instead of the calibrator display. The best dry-block calibrators can directly read PRT standards to improve their display accuracy. A good example is the Field Metrology Well process version.



- Typical system uncertainty can be as good as $\pm 0.05^\circ \text{C}$
- Better than display uncertainty by nearly a factor of five

Tip #8 Use a dry-well or metrology well to eliminate messy fluids

FLUKE®


Calibration

- One great thing about dry-wells is they are dry. That means you don't have to deal with a lot of messy fluids. This can be very helpful if cleanliness is one of your chief requirements. Of course there are ways to keep bath fluids from becoming a mess, but why bother if you don't have to?
- Fluke Calibration 9170 Series Metrology Wells are so accurate they can be used as an alternative to a calibration bath in many applications. We use Metrology Wells in our lab for certain calibrations, and you can do that too or take them onsite.



Tip #9 Conveniently check devices onsite with a handheld dry-well

- If you're just getting started with temperature calibration you probably want to look at the 9100S dry-wells. Anyone can learn to use one in less than 15 minutes, they are inexpensive, and they literally fit in the palm of your hand. You can use them to easily check RTDs, thermocouples and small dial thermometers because the display accuracy is ± 0.25 °C.



9100S fixed-block options. Order number 9100S-A, 9100S-B, 9100S-C, or 9100S-D for the desired block option.



Tip #10 Capitalize on your intuition with a graphing digital thermometer

- The best way to understand your data is to see it. The best digital thermometers help you visualize your data. A good example is the Fluke Calibration 1524 Handheld Reference Thermometers or 1586A which let you graph your data in real time. It's easy to know when to take a measurement if you can see for yourself the temperature is stable



Tip #11 Read multiple thermometers simultaneously





There's more than one reason why measuring multiple thermometers at the same time could be a good idea. One is that you can be more productive if you can calibrate multiple devices in parallel rather than sequentially. Another reason for simultaneous measurement can be accuracy. If your temperature source is not very stable try measuring the reference and the device under test at the same time. Measuring both at the same time can reduce the uncertainty in your measurement by eliminating time dependent temperature differences. With four independent measurement circuits the Fluke Calibration 1529 reads up to 4 RTDs, thermistors, or thermocouples Simultaneously 1586A reads up to 40 channels, as 20 RTDs, thermistors, or 40 thermocouples



1586A Super DAQ

40 input channels...
(not including DCI and DMM channels)



...and up to 10 channels per second

Tip #12 Compensate for ambient temperature variation

FLUKE®

Calibration

One difference between working onsite and working in the lab is that temperature control is rarely very good on the shop floor. Environmental conditions are typically unstable, having wide temperature variations.



That's why each 914X Field Metrology Well has a built-in gradient-temperature compensation that adjusts control characteristics to ensure stable performance in unstable environments.

In fact, all specifications are guaranteed over the environmental temperature range of 13 °C to 33 °C.




Tip #13 Cover more workload with removable inserts

- If you are using a dry-well calibrator and you have to calibrate a probe that does not fit snugly into one of the wells, you still have some options, but putting the probe into a well that's too large with an air gap around the sheath is not one of them. What you need is another insert with a correctly sized hole. Interchangeable removable inserts make it possible to calibrate a wider variety of probes without giving up on good results. You have the option of ordering interchangeable inserts with any Fluke Calibration dry-well except the 9100S



Immersion Depth of Thermometers in Baths

- Rule of Thumb
- Immersion Depth = 20 X the diameter + sensor length
- Example:
 - for a thermometer diameter of .25 inches and sensor length of 1.25 inches
 - Immersion depth = 20 X .25 + 1.25 = 6.25 • inches



Tip #14 Automate Temperature Calibration without Software



- Use the 1586A Super-DAQ to automate temperature sensor calibration


The 1586A Super-DAQ Precision Temperature Scanner provides a unique feature for automating sensor calibration that can greatly increase your lab productivity—without a PC and software.

When the Super-DAQ is connected to a Fluke Calibration dry-well or fluid bath, it can control the temperature source to run the calibration automatically. You simply program the number of set-point temperatures and their values, select a scan sequence, assign a reference channel, and set the required stability band

One temperature source can be connected to the Super-DAQ at a time. The Super-DAQ can control almost all models from Fluke Calibration



1586A Example: Calibrate Temperature Probes



1. Connect Dry-Well to 1586A's control port (on back) with serial cable
 - Cable supplied with all Fluke Dry-Wells
2. Insert Reference and probe to be calibrated
3. Connect all probes to 1586A
4. Configure test on 1586A
5. Start the test
6. Results stored on 1586A internal memory or external USB memory

Read the "Automated Temperature Sensor Calibration with the 1586A Super-DAQ" Application Note (6002875A) for more information

1586A Setup

- All setup is done from the 1586A
 - Configurations can be named and stored in memory for quick recall and consistency
- Setup measurements
- Setup test type
 - Set points
- Start test
 - Several options to monitor progress

CHANNEL SETUP 2015-05-22 13:32:34

Setup File: DEMO_WWM Module: [green bar]

Ch 001 Channel Status: On
 Ch 101 Function: PRT-PT385
 Ch 102 Label:
 Ch 103 Alarm 1: Off
 Ch 104 Alarm 2: Off
 Ch 105 Mx+B: Off
 Ch 106
 Ch 107

Edit Channel Off Copy Channel **Test Setup** Save Setup

1586A Setup


- All setup is done from the 1586A
 - Configurations can be named and stored in memory for quick recall and consistency
- Setup measurements
- Setup test type
 - Set points
- Start test
 - Several options to monitor progress

The screenshot displays the 'CHANNEL SETUP' interface. At the top, a yellow header bar contains 'CHANNEL SETUP' and the date/time '2015-05-22 13:32:56'. Below this, a blue bar shows 'Setup File: DEMO_WWM' and 'Module: [green bar]'. The main area lists channels from Ch 122 to Ch 207. Ch 201 is selected and highlighted with a grey arrow. To the right of the selected channel, the following settings are displayed: 'Channel Status: On', 'Function: Thermocouple-K', 'Label: UUT1', 'Alarm 1: Off', 'Alarm 2: Off', and 'Mx+B: Off'. At the bottom, a row of five buttons is visible: 'Edit Channel', 'Off', 'Copy Channel', 'Test Setup' (highlighted in yellow), and 'Save Setup'.

Channel	Status	Function	Label	Alarm 1	Alarm 2	Mx+B
<input type="checkbox"/> Ch 122	Channel Status: On					
<input checked="" type="checkbox"/> Ch 201	Channel Status: On	Function: Thermocouple-K	Label: UUT1	Alarm 1: Off	Alarm 2: Off	Mx+B: Off
<input checked="" type="checkbox"/> Ch 202						
<input checked="" type="checkbox"/> Ch 203						
<input type="checkbox"/> Ch 204						
<input type="checkbox"/> Ch 205						
<input type="checkbox"/> Ch 206						
<input type="checkbox"/> Ch 207						


1586A Setup

- All setup is done from the 1586A
 - Configurations can be named and stored in memory for quick recall and consistency
- Setup measurements
- Setup test type
 - Set points
- Start test
 - Several options to monitor progress



1586A Setup

- All setup is done from the 1586A
 - Configurations can be named and stored in memory for quick recall and consistency
- Setup measurements
- Setup test type
 - Set points
- Start test
 - Several options to monitor progress

TEST SETUP		2015-05-22 13:33:14		
Setup File: DEMO_WWM	Module:			
Trigger Type: Automated Test				
Auto Recording: On				
File Destination: Internal				
Sample Rate: Slow				
Data Security: Off				
Temperature Unit: °C				
Align Channels		Edit		Back

1586A Setup


- All setup is done from the 1586A
 - Configurations can be named and stored in memory for quick recall and consistency
- Setup measurements
- Setup test type
 - Set points
- Start test
 - Several options to monitor progress

The screenshot displays the 'TEST SETUP' interface. At the top, a yellow bar shows 'TEST SETUP' on the left and the date/time '2015-05-22 13:33:52' on the right. Below this, a blue bar contains 'Setup File: DEMO_WWM' and 'Module: [green bar]'. The main area lists the following settings: 'Trigger Type: Automated Test', 'Scan Count: 5', 'Sequence: Linear', 'Reference Channel 1: Ch 001', and 'Reference Channel 2: None'. The 'Control Source' is set to 'On', which is highlighted with a yellow background. At the bottom, a row of five blue buttons is visible: 'Setpoints', an empty button, 'Edit', another empty button, and 'Back'.

TEST SETUP	2015-05-22 13:33:52			
Setup File: DEMO_WWM	Module: [green bar]			
Trigger Type: Automated Test				
Scan Count: 5				
Sequence: Linear				
Reference Channel 1: Ch 001				
Reference Channel 2: None				
Control Source: On				
Setpoints		Edit		Back

1586A Setup


- All setup is done from the 1586A
 - Configurations can be named and stored in memory for quick recall and consistency
- Setup measurements
- Setup test type
 - Set points
- Start test
 - Several options to monitor progress

TEST SETUP		2015-05-22 13:34:01
Setup File: DEMO_WWM		Module: 
Setpoint 1	Setpoint: 50.0 °C	
Setpoint 2	Tolerance: 1.0 °C	
Setpoint 3	Stability: 0.1 °C	
Setpoint 4	SoakTime: 00:10:00	
Setpoint 5		

New	Insert	Edit	Delete	Back
-----	--------	------	--------	------

1586A Setup

- All setup is done from the 1586A
 - Configurations can be named and stored in memory for quick recall and consistency
- Setup measurements
- Setup test type
 - Set points
- Start test
 - Several options to monitor progress

SCAN		2015-05-22 13:34:45		
Setup File: DEMO_WWM		Module: 		
Trigger Type: Automated Test				
Scan Status: Inactive				
Point Number: 1 / 5				
Setpoint: 50.0000 °C				
Start Scan		Data	Graph	Monitor

1586A Setup

- All setup is done from the 1586A
 - Configurations can be named and stored in memory for quick recall and consistency
- Setup measurements
- Setup test type
 - Set points
- Start test
 - Several options to monitor progress


SCAN Recording ⚠ 2015-05-22 13:35:07
Setup File: DEMO_WWM Module: 

Trigger Type: Automated Test
Start Time: 2015-05-22 13:34:53
Scan Status: Settling
Point Number: 1 / 5
Setpoint: 50.0000 °C

Stop Scan Pause Scan Data Graph Monitor


1586A Setup

- All setup is done from the 1586A
 - Configurations can be named and stored in memory for quick recall and consistency
- Setup measurements
- Setup test type
 - Set points
- Start test
 - Several options to monitor progress



1586A Setup

- All setup is done from the 1586A
 - Configurations can be named and stored in memory for quick recall and consistency
- Setup measurements
- Setup test type
 - Set points
- Start test
 - Several options to monitor progress



1586A Results



- Files stored in CSV format, easily read by Excel or other analysis or reporting tools
- Two files stored with each test
 - Setup.csv – records all configuration details
 - Data.csv – all measurement data with time tag

Open Detect							
	A	B	C	D	E	F	G
1	Test Setup	DDMO_WWM					
2	Start Time	5/22/2013 14:20					
3	User	GUEST					
4							
5	Instrument						
6	Hardware	Model	Serial Number	Version	CAL Date		
7	Mainframe	1586A	28120007	L02+L02	1/9/2013		
8	Slot1	1586-1586	25440004	(n/a)	10/14/2013		
9	Slot2	1586-1588	27830004		5/22/2014		
10							
11	Analogue Channels						
12	Channel	Label	Function	Open Detect	Wire	Sensor Type	Cold Junction
13	Ch001		TEMP ROD	(n/a)	WR04	AJ85	(n/a)
14	Ch002	UUT1	TEMP TC	ON	(n/a)	4	INT
15	Ch003	UUT2	TEMP TC	ON	(n/a)	4	INT
16	Ch003	UUT3	TEMP TC	ON	(n/a)	4	INT
17							
18	Test Setup						
19	Setup Name	Trigger Type	Auto Record	File Destination	Sample Rate	Security	Scan Count
20	DDMO_WWM	AUTO	ON	INT	SLOW	OFF	1 (n/a)
21							
22	Set Points						
23	Point	Setpoint	Tolerance	Stability	Soak Time		
24	1	90.00	1.00	0.30	600		
25	2	100.00	1.00	0.30	600		
26	3	150.00	1.00	0.30	600		
27	4	200.00	1.00	0.30	600		
28	5	250.00	1.00	0.30	600		

K29							
	A	B	C	D	E	F	G
1	Record #	Time	Ch 001 (C)	Ch 201 (C)	Ch 202 (C)	Ch 203 (C)	
2	1	2:49:28 PM	50.03	49.84	50.19	49.64	
3	2	2:49:43 PM	50.03	49.84	50.19	49.64	
4	3	2:49:59 PM	50.03	49.84	50.19	49.64	
5	4	2:50:14 PM	50.03	49.83	50.18	49.64	
6	5	2:50:29 PM	50.03	49.83	50.18	49.63	
7	6	3:10:03 PM	100.09	100.08	100.05	99.72	
8	7	3:10:18 PM	100.09	100.08	100.05	99.72	
9	8	3:10:33 PM	100.09	100.08	100.05	99.72	
10	9	3:10:49 PM	100.09	100.08	100.05	99.72	
11	10	3:11:04 PM	100.08	100.08	100.05	99.72	
12	11	3:29:14 PM	150.12	151.03	150.97	150.66	
13	12	3:29:29 PM	150.12	151.03	150.97	150.67	
14	13	3:29:44 PM	150.12	151.03	150.97	150.67	
15	14	3:30:00 PM	150.13	151.04	150.98	150.67	
16	15	3:30:15 PM	150.13	151.03	150.98	150.67	
17	16	3:48:45 PM	200.15	201.28	200.75	200.84	
18	17	3:49:00 PM	200.15	201.28	200.75	200.84	
19	18	3:49:16 PM	200.14	201.27	200.74	200.83	
20	19	3:49:31 PM	200.14	201.27	200.75	200.83	
21	20	3:49:46 PM	200.15	201.28	200.75	200.84	
22	21	4:08:08 PM	250.24	251.18	250.74	250.47	
23	22	4:08:23 PM	250.24	251.17	250.73	250.47	
24	23	4:08:39 PM	250.23	251.15	250.72	250.46	
25	24	4:08:54 PM	250.22	251.14	250.71	250.45	
26	25	4:09:09 PM	250.22	251.15	250.72	250.46	
27							

Questions?

FLUKE®

Calibration

QUESTIONS

