

The Most Trusted Tools in the World.

Laser Alignment and the Fluke 830

Technical Presentation – Technical Training

Benefits – why is it needed

- Proactive Maintenance
- Benefits of Precision Shaft Alignment

Alignment Principles and Laser Technology

- What is shaft alignment / Why is it needed / Why laser alignment


Fluke 830 Overview - technology

- Fluke 830 Hardware overview
- Key Features and Benefits
- Quick, Easy, Step by step, Precision alignment (QRG)
 - Overview, Mount Brackets, Setup, Measure, Diagnose, Correction
- Other: Soft Foot, Save, Report, Extend, Switch, Clock, Vertical, Settings
- Appendix – Sensor Cable, Updates
- Technical Specs
- Support - Frequently Asked Questions
- Optional items
- Service / Calibration

Fluke tools help you keep your plant running


- 1) Fluke Thermal Imager and Vibration Meter finds machine problems
- 2) Fluke Vibration Tester diagnoses fault, severity and repair recommendation
- 3) Fluke Connect shares data between users - allows planner to generate work order
- 4) Fluke Alignment Tool corrects the problem
- 5) Fluke Vibration Tester checks the machine is fixed

Fluke Thermal Imager



Problem found

Fluke Vibration Tester




Problem identified & repair recommended

Fluke Connect

Work order generated

Fluke Alignment Tool



Problem corrected

Fluke Vibration Tester




Machine checked - good

Machine returned to service
– no production loss

Benefits of Proactive Maintenance



FLUKE®

- **Predictability**: give maintenance staff time to schedule required repairs and acquire parts.
- **Safety**: take faulty equipment offline before a hazardous condition occurs
- **Revenue**: fewer unexpected and serious failures, helping to prevent production stoppages that cut into the bottom line.
- **Increased maintenance intervals**: life of equipment can be extended and maintenance can be scheduled by need.
- **Reliability**: fewer unexpected or catastrophic failures - problem areas can be anticipated before failure
- **Peace of mind**: builds confidence in maintenance schedules, budgeting, and productivity estimates.



Why precision alignment?

- Reduce your energy consumption
- Fewer failures of seals, couplings and bearings
- Lower temperatures of bearings and coupling
- Lower vibration levels – that result in fewer mechanical faults
- No shaft cracking or failures
- No loose foundation bolts



1. The flexible coupling heats up and the machine develops higher temperatures, especially at the bearings.
2. The high reaction forces are drastically reduced after precision alignment and so are the faults that lead to asset failure and production losses.

Applications/Users/Industries

Typical Applications:

- Precision alignment of rotating machinery

Value Proposition:

- Energy savings
- Prevent Unplanned Downtime
- Reduce Component Replacement Costs
- Reduce Repair Time
- Easier to Use

Industries:

- Chemical/Petrochemical
- Oil and Gas
- Power
- Automotive
- Pulp, Paper and Printing
- Food processing
- Marine
- Steel
- Mining
- Machinery manufacturing
- Cement
- Service organizations


Target Segment:

- Mechanical Maintenance Technicians
- Facilities Engineers
- Existing Fluke 805 and 810 users

Preliminary Positioning:


- Misalignment is costing you \$\$,\$\$\$
- Fluke Laser alignment is the most precise
- Fluke Laser Alignment is the fastest
- Rulers and Dials are antiquated tools

What is shaft alignment ?




at the point of power transfer from one shaft to another, the axes of rotation of both shafts should be colinear when the machine is running under normal operating conditions



The 4 alignment parameters




Vertical angularity



Vertical offset




Horizontal angularity



Horizontal offset

Angularity and gap

Angularity means the angle between two rotation axes



The angle is usually given as a **gap per working diameter**.

A 6" (152.4 mm) coupling open at the top by 0.005" (0.127 mm)

gives an angle between shaft axes of 0.83 mrad.


$$\theta = \text{gap} / \text{working diameter}$$

$$\theta = 0,127/152,4 = 8,33 \cdot 10^{-4} \text{ rad} = 0,83 \text{ mm/m}$$

Note:


1 mrad = 1 thousandth of an inch per inch

1 mrad = 1 mm / m




Offset

Offset means distance between rotation axes at a given point





Offset value varies depending upon the location where the distance between two shaft rotation axes is measured



Alignment condition

- Alignment condition is always a combination of angularity and offset
- Machine has to be corrected in both vertical and horizontal planes
- 4 values are required to fully describe the alignment condition:
 1. Vertical angularity (or gap per diameter)
 2. Vertical offset
 3. Horizontal angularity (or gap per diameter)
 4. Horizontal offset
- **Offset refers to distance between shaft rotation axes at coupling center**



Coupling tolerance

An often quoted comment is “...**why bother to align the machine when it is fitted with a flexible coupling designed to take misalignment?**”

It is true that flexible couplings are designed to take misalignment, typically up to **10mm** or more radial offset of the shafts. But the **load imposed on shafts, and thus the bearings and seals increase dramatically due to the reaction forces created within the coupling when misaligned.**


Symptoms of misalignment

- Excessive radial and axial vibration.
- High casing temperatures at or near the bearings or high discharge oil temperatures.
- Excessive amount of oil leakage at the bearing seals.
- Loose foundation bolts, shim packs or dowel pins.
- Loose or broken coupling bolts.
- Some flexible coupling designs run hot under misalignment conditions. If it is an elastomeric type, look for rubber powder inside the coupling shroud.
- Similar pieces of equipment are vibrating less or seem to have a longer operating life.
- Unusually high number of coupling failures or they wear quickly.
- The shafts are breaking (or cracking) at/or close to the inboard bearings or coupling hubs.
- Excessive amounts of grease (or oil) on the inside of the coupling guard.


Pre-alignment checklist




Machines tagged out -
Padlock on switchgear



Pipe/bracket
strain
eliminated?




Base OK?



Shafts OK?
Run out, bending,
bearing play?




Shims OK?
(maximum 4 shims!)



Coupling OK?
Proper fit on shaft, looseness,
eccentricity, flexible elements OK?




Bent bolts?
Cupped washers?



Soft foot
eliminated?






Hold-down bolts,
jacking bolts
lubricated?




Targets,
tolerances
established?

Machine mobility – feet corrections





Once alignment condition found, a correction is recommended

Consequences of misalignment




Common alignment methods


Straightedge/Feeler gauge
Resolution 1/10 mm




Dial indicator
Resolution 1/100 mm



Laser-optical alignment
Resolution 1/1000 mm




Straightedge and feeler gauges



- Limited resolution of the human eye:
0.1 mm /0.004”
- Coupling alignment - not shaft alignment
- Prone to coupling fitting errors
- Trial and error corrections
- No documentation
- Far too inaccurate for most machines

Dial indicators



- Resolution (typical): 0.01 mm / 0.0004"
- Bracket sag
- Mechanical play
- Possible sign error
- Calculations complicated
- Requires high user experienced.

How accurate are dial indicator readings?

Sagging indicator brackets

Sag should always be measured before actual alignment readings are taken irrespective of how solid the bracket appears.



Low resolution

Up to 0.005 mm rounding error may occur with each reading – which easily results in an error of up to 0.04 mm in the calculated results.




Sticking/jumping dial hands

Sometimes the indicator must be tapped in order for the needle to settle on its final value.




Play in mechanical linkages

Slight amounts of looseness may not be noticed, yet produce large errors in results.




Reading errors

Human errors occur all too often when dials must be read under cramped, poorly-lit conditions and severe time constraints.




Tilted dial indicator

The indicator may not be mounted perpendicular to the measurement surface so that part of the displacement reading is lost.




Axial shaft play

This can affect face readings taken to measure angularity unless two axially mounted indicators are used.





Shaft alignment methods: Dial indicators

Rim and face method



Reverse indicator method




Inner scale has one division per rotation

Outside scale can be rotated for zeroing


Dial indicators - Reverse method using a graph

e.g. for vertical direction



All values are shown in mm.

The indicator bracket sag was -0.10 mm. The total indicator readings (TIRs) after correction for bracket sag are thus:




The TIR values must be divided by 2 to determine the true shaft offset values in the planes of the dial indicators:


$$\text{Offset S} = +0.70 / 2 = +0.35 \text{ mm}$$

$$\text{Offset M} = -1.40 / 2 = -0.70 \text{ mm}$$

The offsets are plotted on the graph as shown below :




Laser alignment methods




- Resolution of 1/1000 mm (0.00004")
- Universal bracket
- No bracket sag influence
- Human error free
- Accurate measurement
- Graphical result display:
No misinterpretation
- Alignment evaluation
- “Live” corrections
- Documented results

Parallarity




Measurement principle


Parallarity




Angularity




Angularity





- The **auto-collimating laser optics system** is less susceptible to backlash

Measurement principle




Laser principle

- One sensor / prism
- Laser: semiconductor laser
- One roof prism as reflector
- Quick setup and laser beam adjustment
- Built-in electronic inclinometer


Measurement principle

Highly accurate linearization = highly accurate alignment on first attempt!

'Raw' detector response




Linearized response




(2.4, 6.3) -----> (3.0, 6.0)

Calibration data stored in transducer



Offset and angularity from the calculation ellipse



(5.4, 6.3) -----> (3.0, 6.0)




- Fluke 830 Hardware overview
 - Sensor and Prism
 - Measurement principle
- Key Features and Benefits
- Quick, Easy, Step by step, Precision alignment (QRG)
 - Overview of 830
 - Steps of Precision Alignment
 - ✓ Mount Brackets - preparation
 - ✓ Setup – enter machine dimensions
 - ✓ Measure – take 3 of 8 available positions
 - ✓ Diagnose – alignment results, condition, feet adjustments
 - ✓ Make Corrections – vertical, then horizontal, save & print
 - Other: Soft Foot, Save, Report, Extend, Switch, Clock, Vertical, Settings
 - Appendix – Sensor Cable, Updates, Specs, Options, Service / Calibration

Fluke 830 Alignment – hardware overview

FLUKE®




Bluetooth




Alignment tool

Single Laser: sensor - prism



Laser sensor and prism



Precision prism reflects beam back

Laser Alignment Technology - Sensor

FLUKE®

CAUTION
DON'T STARE
INTO BEAM

Laser type
AlGaInP
semiconductor
laser


Wavelength
675 nm
(red, visible)

Safety class
Class 2

Beam power
< 1mW


Green LED indicates
beam adjustment
laser is on

Red LED indicates sensor is
powered and laser is on



Out of
range


End



Detector surface


Linearized area

Scratch resistant lens




Wireless module ON/OFF switch

Wireless module slides onto
the support posts




1. Wireless module held in place
by friction fit



2. Tighten the yellow knobs;
attach cable connector from
wireless module


Laser Alignment Technology - Prism



Fluke 830 - Key features and benefits

FLUKE®

- 1. **Single Laser Beam:** auto-collimating laser optics system is less susceptible to backlash => less error means more accurate and more repeatable
- **Rugged design:** ergonomic, robust, and protected from dust & water
- **Best in Class Repeatability:** patented single laser, precision manufactured parts and high quality fasteners coupled with extremely accurate lab calibrations give you added confidence in your measurement results.
- **Wireless:** Bluetooth communication removes cables that take longer to use
- **Integrated batteries:** Li-Ion rechargeable for long life



Fluke 830 Key features and benefits

FLUKE®

2. Intuitive guided user interface: eliminates guesswork, increases accuracy

Many tools are simple, but take time to re-learn what the numbers mean – you need answers




Shaft alignment focus: remove high-end programs not needed

3 simple steps: walk you through steps (like 810)

1. Setup – step by step to input the machine dimensions (saved from last time)

2. Measure – starts when shafts rotated – take readings from 3 sectors when turn green on screen.

3. Diagnose – actual correction numbers given: use precision shims to save time and precision alignment every time




Fluke 830 Key features and benefits

3. Compass Measurement Mode: enables flexible, reliable and repeatable measurements using a built-in activated electronic inclinometer.

Answers NOT just data: Any tool can give numbers – even dial indicators, but you need answers to quickly align the machine and get it running fast.

“All in One” result screen shows both coupling results and feet corrections (vertical and horizontal)

4. Dynamic Machine Tolerance Check: provides continuous evaluation of alignment adjustments to know when machine in acceptable range. 4-level color severity scale indicates when alignment is acceptable – Green = excellent, Yellow = acceptable, Orange = out of tolerance, Red = grossly misaligned.



Tolerance table mm

Press ENTER to disable tolerances.

| Diameter: 50 mm | | Enabled |
|-----------------|---------------------------|---------------------------|
| RPM | Acceptable | Excellent |
| 750 | Gap: 0.06 Offset: 0.19 | Gap: 0.04 Offset: 0.09 |
| 1500 | Gap: 0.03 Offset: 0.09 | Gap: 0.02 Offset: 0.06 |
| 1770 | Gap: 0.03 Offset: 0.08 | Gap: 0.02 Offset: 0.05 |
| 3000 | Gap: 0.02 Offset: 0.06 | Gap: 0.01 Offset: 0.03 |

Fluke 830 Key features and benefits

5. Data Protection ensures your data is there when you need it with auto save and resume capability




Reports: document work done – print report “as found “and “as left”

6. Unique Extend Mode: offers unlimited measurement ranges to handle gross misalignment scenarios with best accuracy.

How big is the sensor? The real question should be: how big is the misalignment?

- Don't waste time with a rough alignment or pay for expensive big, bulky sensors
- Virtually increases the sensor area when needed

| Fluke 830 LASER ALIGNMENT TOOL Report | |
|---------------------------------------|---------------------------------------------------------------|
| File info | |
| Filename: | sample |
| Created: | 20-September-2004, 13:02:42 |
| Measured: | 20-March-2007, 12:38:51 |
| Comment: | |
| Machine dimensions | |
| Static: | Value: Unit: |
| Coupling | Coupling diameter: 10.000 [inch] |
| | Distance from sensor to prism: 45.000 [inch] |
| | Distance from sensor to coupling centre: 22.500 [inch] |
| | Distance to right machine: 65.000 [inch] |
| | RPM: 1800 RPM |
| Movable: | Distance from 1 to 2 Feet: 75.250 [inch] |
| Dimensions [inch] | |
| | RPM 1800 |
| | 45.000 |
| | 22.500 |
| | 65.000 75.250 |
| | Ø 10.000 |
| Machine coupling diagnose | |
| Actual: | Value: Unit: |
| Results of Sweep Measurement | |
| Vertical: | |
| Gap | -0.7 [mil] |
| Offset | -2.2 [mil] |
| Vertical tolerance: | |
| Horizontal: | |
| Gap | -0.4 [mil] |
| Offset | +1.3 [mil] |
| Horizontal tolerance: | |
| Machine foot corrections | |
| Static: | Vertical: Horizontal: Unit: |
| Movable: | |
| Foot 1 | -2.4 -3.7 [mil] |
| Foot 2 | -7.7 -6.5 [mil] |
| Printed: | 28-March-2014, 13:29:58 Ver.: 1.00 S/N: 65431612 Page: 1 of 2 |



Static Mode: align vertical, uncoupled and non-rotatable shafts

Soft foot: check to make sure misalignment not from foundation problem

Fluke 830 Alignment Tool

FLUKE®



- Robust design – the computer is protected against dust and water in compliance with classification IP 65
- Color TFT ¼ VGA screen
- 'Lithium-ion polymer rechargeable battery
- Wireless communication with sensor via Bluetooth
- Keyboard including Setup, Measure, Diagnose, SF & Move keys
- Interfaces
 1. USB PC/printer port, charging socket
 2. Sensor port RS 232
- Multicolor LED for battery status, wireless connection & tolerance condition



Fluke 830 Alignment Tool - package

FLUKE®



Item Description

1. Fluke 830 Laser Alignment Tool
 2. Storage case
 3. Sensor including dust cap and wireless module cable
 4. Prism including dust cap
 5. Chain-type bracket (2X) – each comprises two support posts and chain
 6. Wireless module
 7. Sensor cable
 8. Adapter/charger
 9. PC cable
 10. USB cable
 11. USB memory stick
 12. Cleaning cloth
- Quick reference guide
Safety sheets
Users manual on CD

Options

- Magnetic Brackets
- Precision Shim Kit



Overview of 830



| Item | Element | Function |
|------|--------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------------------------------|
| 1 | | The 'Setup' key opens the machine dimensions screen. |
| 2 | | The 'Measure' key is used to start the measure process. |
| 3 | | The 'Diagnose' key is used to display measured and corrective alignment results. |
| 4 | LED (battery status/ wireless communication indicator) | Shows the battery and wireless communication statuses. |
| 5 | USB PC/printer port (grey) | The port is used to charge the Product, print and save measurement files, carry out firmware updates as well as display screen on a PC. |
| 6 | Ambient light sensor | Use to regulate the Product's display brightness. |
| 7 | Sensor port (blue) | The port is used to connect to Product when the wireless module is not available |
| 8 | LED (alignment condition and laser beam adjustment) | Used for laser beam adjustment and as a tolerance check for measured alignment condition. |
| 9 | | The 'Menu' key is used to access the main menu which possesses the Product's useful functions. |
| 10 | | The 'On' key is used to switch the Product on. The Product is switched off via the main menu item 'Turn off'. |
| 11 | | The navigation keys are used to navigate through the program steps. |
| 12 | | The 'Enter' key is used to confirm entered values and access any selected item. |
| 13 | | The 'Back' key is used to return to previously selected screen. |
| 14 | | The 'Clear' key is used to delete information entered inadvertently. |
| 15 | | The data entry keys are used to enter machine dimensions and file name. |

Quick, Easy, Step by step, Precision alignment

FLUKE®

Quick Reference Guide – included with Fluke 830

Overview, Mount Brackets, Setup, Measure, Diagnose, Make Correction

FLUKE®

830 Laser Shaft Alignment Tool

Quick Reference Guide

Warning
To prevent possible electrical shock, fire, or personal injury, read the "830 Safety Sheet" before you use this Product.

Go to www.fluke.com to register your product, download manuals, and find more information.



Overview of 830



On


Vertical
Gap: -0.04 mm
Offset: -0.05 mm
Horizontal
Gap: 4.0 mm
Offset: 4.0 mm

Make menu
Factory default: 0.000
Keyboard bias: 0.000
Power source: Li-ion L90
Battery level: 70 %
Elastic force: ALWAYS ROBBING
Vertical: 0%

Configuration menu
Auto stop: ON
Auto stop: OFF
Auto stop: ON

Factory Settings
FLUKE 830 LASER SHAFT ALIGNMENT TOOL
FLUKE 830 LASER SHAFT ALIGNMENT TOOL
FLUKE 830 LASER SHAFT ALIGNMENT TOOL
FLUKE 830 LASER SHAFT ALIGNMENT TOOL

Mount Bracket on Shaft



1. Mount the bracket onto the shaft.

2. Tighten the screws to secure the bracket.

3. Adjust the bracket to the correct position.

Anchor peg

1 X2

2


3

4

5

6

Step 1 Setup: Enter Machine Dimensions



Distance between feet of the right machine: 350 mm

1 Take dimensions

2 Enter dimensions

Quick, Easy, Step by step, Precision alignment

Quick Reference Guide – included with Fluke 830

Overview, Mount Brackets, Setup, Measure, Diagnose, Make Correction

Step 2 Measure: Take 3 Readings

- Menu
Measurement Options
Compass Mode, Clock Mode, Averaging, Extend, Sensor Selection
- Adjust prism
- Take measurement when green
Measure - COMPASS MODE
Press ENTER to start measurement.
Laser READY
WID: 55500050
0 points
- Rotate Sensor/Prism Modules
- Repeat - 3 of 8 sectors
Measure - COMPASS MODE
Press ENTER to take a point.
Laser READY
WID: 55500050
1 points
- Measure - COMPASS MODE
Press ENTER to take a point.
Laser READY
WID: 55500010
2 points

Step 3 Diagnose: Make Feet Correction

| Diagnose | | Adjustment | |
|---------------------|-----------|--------------|-------------|
| Current measurement | | Adjustment | |
| Vertical | Gap -0.04 | Offset -0.05 | -0.02 -0.15 |
| Horizontal | Gap +0.22 | Offset +0.08 | +0.29 -0.98 |

Adjustment needed

Alignment condition

| Tolerance | Tolerance Bar | LED Color |
|----------------------|---------------|-----------|
| Excellent Tolerance | Green | Green |
| Acceptable Tolerance | Yellow | Yellow |
| Out-of-Tolerance | Orange | Orange |
| Grossly Misaligned | Red | Red |



Recheck and Tighten Bolts

Check for Soft Foot

Overview of 830 - Quick Reference Guide

FLUKE®

- Non-removable 7.4 V 2.6 Ah Lithium-ion polymer rechargeable battery, charged via USB port with adapter/charger
- Operation of up to 17 hours (33% active measurement, 33% computation, 33% 'sleep' mode)
- *Before charging, battery should be discharged as much as possible*
- *Charge the battery from 0% to 100% capacity takes approximately 4 hours*
- LED flashes green at initialization and during the charging process
- A constantly lit green LED denotes that the battery is fully charged.
- Charge level of the battery is displayed under the menu item 'Device settings'



Overview of 830 - Quick Reference Guide

FLUKE®

Overview of 830

On

SETUP

MEASURE

DIAGNOSE

MENU

ENTER

Configuration Menu

Device Settings

Setup mm
Distance between feet of the right machine.
350 mm

Measure - COMPASS MODE mm
Press ENTER to take a point.
Laser READY
WID: 5500010
2 points

Diagnose mm
Current measurement Adjustment
Vertical
Gap -0.04
Offset -0.05 -0.02 -0.15
Horizontal
Gap +0.22
Offset +0.08 +0.29 +0.98

Menu Main menu mm
Left Machine Coupling Tol. Right Machine Move Soft Foot
File Measure Options Print Report **Config** Turn Off


Menu Configuration Menu mm
Device Settings Regional Settings Default Settings
Printer Configuration About

Configuration Menu Device Settings mm
Press LEFT,RIGHT to adjust,ENTER toggles
Brightness: **AUTO**
Keyboard beep: OFF
Power scheme: LONG LIFE
Battery level: 70 %
Resume policy: ALWAYS RESUME
Wireless: ON



Alignment tool – Main Menu



Press
Menu



Press
Enter



Press Down Arrow



Alignment tool

FLUKE®



Step 3

DIAGNOSE

Diagnose mm

Current measurement Adjustment

| | | |
|------------|-------|-------------|
| Vertical | | |
| Gap | -0.01 | |
| Offset | -0.16 | +0.10 +0.04 |
| Horizontal | | |
| Gap | -0.00 | |
| Offset | +0.07 | -0.09 -0.11 |

Step 2

MEASURE

Measure - COMPASS MODE mm

Press ENTER to take a point.

Laser READY

WID: 59500050

2 points

Step 1

SETUP

Setup mm


Distance between feet of the right machine.

280 mm






Steps of Precision Alignment

- ✓ Mount Brackets - preparation
- ✓ Setup – enter machine dimensions
- ✓ Measure – take 3 of 8 available positions
- ✓ Diagnose – alignment results, condition, feet adjustments
- ✓ Make Corrections – vertical, then horizontal, save & print

Mount brackets on shaft in preparation




1. Mount brackets on both sides of the coupling tightly on shaft




Slide wireless module and sensor on posts

FLUKE®





2. Mount wireless module and sensor on “Left machine” – usually Stationary
- Mount as low as possible but high enough for beam to clear coupling flange

After connecting sensor to wireless module, switch on wireless module





Fasten the sensor onto the support posts by tightening the yellow knobs




The 90-degree sensor cable connector is attached to the wireless module

| LEDs | Battery life |
|-----------------------------------------------------------------|--------------|
| 3 LEDs | 75%–100% |
| 2 LEDs | 50%–75% |
| 1 LED | 25%–50% |
| Blinking slowly - under 25% | |
| Blinking fast - critical phase (2 x AA disposable batteries) | |

Slide prism on posts





3. Mount prism on “Right machine” the same height as sensor. Center the laser dot on the prism dust cap



Step 1 - Setup Machine



Press Setup **SETUP**




1 Measure machine dimensions

- 1. Sensor to prism
- 2. Sensor to center of coupling
- 3. Coupling diameter (default is 100 mm / 10")
- RPM
- 4. Center of coupling to front foot (right machine)
- 5. Front foot to back foot (right machine)

After the last required dimension has been entered, the measurement screen appears.

2 Enter dimensions Step by step



Step 2 - Measure Machine




1 **MEASURE**


Press Measure
OR

MENU

Press Menu
and select
Compass Mode




Horizontal = Compass Mode; Vertical = Clock Mode



2

Adjust prism –
center reflected
laser beam using
thumbwheel and
adjustment knob





Step 2 - Measure Machine




3 Rotate shaft to first measurement position. Take measurement when sector turns green.

- Notes:*
- Always turn shafts in normal rotation direction of machine
 - Don't touch mounted components




4 Rotate shaft to another sector




Inclinometer automatically determines angle on shaft

Step 2 - Measure Machine


Measure from any 3 of 8 available positions



- ✓ Measure - 1
- ✓ Rotate to another sector
- ✓ Measure - 2
- ✓ Rotate to another sector
- ✓ Measure - 3



5 Take measurement #2 when sector turns green – turns orange when measurement is complete



6 Take measurement #3 when sector turns green

Step 3 – Diagnose Faults




Press Diagnose



Diagnose mm

| Current measurement | | Adjustment | |
|---------------------|-------|------------|-------|
| Vertical | | | |
| Gap | -0.01 | +0.10 | +0.04 |
| Offset | -0.16 | | |
| Horizontal | | | |
| Gap | -0.00 | -0.09 | -0.11 |
| Offset | +0.07 | | |

Alignment results with coupling values, condition and foot adjustment in both vertical and horizontal directions are displayed automatically




Step 3 – Diagnose Faults

“All-In-One” screen


| Diagnose | | mm | |
|---------------------|------------|------------|--------------|
| Current measurement | | Adjustment | |
| A | Vertical | Gap -0.04 | Offset -0.05 |
| B | | | -0.02 -0.15 |
| C | Horizontal | Gap +0.22 | Offset +0.08 |
| D | | | +0.29 98 |

3. Corrections Needed




Align machine
 - move it vertically by shimming feet
 - horizontally by shifting it sideways

1. Misalignment Values



2. Alignment Condition


| Tolerance | Tolerance Bar | LED Color |
|----------------------|---------------|-----------|
| Excellent Tolerance | | Green |
| Acceptable Tolerance | | Yellow |
| Out-of-Tolerance | | Orange |
| Grossly Misaligned | | Red |



Make vertical corrections




| Diagnose | | mm | | Adjustment | |
|---------------------|-------|-------|-------|------------|------|
| Current measurement | | | | | |
| Vertical | | | | | Side |
| Gap | -0.01 | | | | |
| Offset | -0.16 | +0.10 | +0.04 | | |
| Horizontal | | | | | Top |
| Gap | -0.00 | | | | |
| Offset | +0.07 | -0.09 | -0.11 | | |




Once alignment condition is found, a correction is recommended:

- Loosen bolts and shim **first** for vertical correction
- Jack up machine and insert or remove shims of known thicknesses
- Use vertical foot correction values to shim **BOTH** front and back feet
- Positive foot correction values suggest addition of shims
- Negative foot correction values indicate feet are high and remove shims
- Retighten bolts and Re-measure - Use Horizontal live Mode

Make horizontal corrections




Select 'Move' icon




Rotate shaft to any 45° position



Select "Horizontal"




Shim for "Vertical"
Jack for "Horizontal"




Loosen bolts and move machine
in direction of yellow triangles

Watch color-coded tolerance bar.
When green or yellow, tighten feet anchor bolts.


Recheck alignment



Recheck alignment



Save data



Print report to document work

Finally

Switch 830 off, remove components from shafts, and store them in case

Poor repeatability? Possible causes:

- Incorrect or loose bracket mounting; Mounted components move during rotation
- Significant shaft bearing play or coupling backlash
- Soft foot can cause positioning errors that make repeat measurement necessary
- Loose anchor bolts; Uneven shaft rotation; Vibration
- Yellow knobs on sensor loose, or prism not locked into horizontal position
- Sensor is mounted incorrectly or upside down
- Temperature change: machine recently shut down

Other Steps

- ✓ Soft Foot – check before alignment
- ✓ Tolerance Table – know when to stop
- ✓ Save File
- ✓ Report – print “as found” and “as left”
- ✓ Extend Sensor Range for gross misalignment
- ✓ Switch Machine Setup – Left or Right machine
- ✓ Clock Mode – uncoupled, nonrotating, or vertical shafts
- ✓ Averaging
- ✓ Settings – Device, Regional, Printer, About
- ✓ Sensor selection & Laser beam adjustment

Check Soft Foot before alignment


Any cause that results in machine frame distortion when machine is anchored to its foundation is a soft foot. Some of the principal causes are:

- Non-coplanar machine mounting surfaces
- Deformed machine frame or feet
- External forces from connecting piping or brackets
- Improper shimming or soiled machine feet
- Too many shims under a machine foot (maximum of 4 shims)


Forcibly tightening down feet deforms machine frame, causes bent shaft and distorts bearings.

Soft foot should be checked before aligning the shafts.

- Calculate how much each foot has moved as bolt is loosened.
- Results are interpreted and translated into shim thicknesses to be placed under the feet.




Parallel soft foot






Angular soft foot

Soft Foot check



Loosen one motor anchor bolt and take a measurement






Soft Foot check



- Retighten each motor anchor bolt and measure another foot.
- Repeat procedure for each foot.
- Color-coded tolerance bar shows value of the measured soft foot.
- Shimming corrections are necessary

Soft Foot tolerance = 0.06 mm (0.002 inch)



Tolerance Table


Excellent – perfectly aligned ■


Acceptable – still within tolerance ■

Out of tolerance ■

Grossly misaligned ■

| | [RPM] | metric [mm] | inch [mils] |
|--|-------|-------------|-------------|
|--|-------|-------------|-------------|

| Soft foot | any | 0.06 mm | | 2.0 mils | |
|----------------------------------------------------------------------------------------------------------------------------|------|--------------------------------------------------|------------------------------------------------|--------------------------------------------------|------------------------------------------------|
| Short "flexible" couplings Offset  | | Acceptable ■ | Excellent ■ | Acceptable ■ | Excellent ■ |
| | 600 | | | 9.0 | 5.0 |
| | 750 | 0.19 | 0.09 | | |
| | 900 | | | 6.0 | 3.0 |
| | 1200 | | | 4.0 | 2.5 |
| | 1500 | 0.09 | 0.06 | | |
| | 1800 | | | 3.0 | 2.0 |
| | 3000 | 0.06 | 0.03 | | |
| | 3600 | | | 1.5 | 1.0 |
| | 6000 | 0.03 | 0.02 | | |
| 7200 | | | 1.0 | 0.5 | |

| | | | | | |
|-------------------------------------------------------------------------------------------------------------------------------------------------------------|------|------|------|------|------|
| Angularity coupling gap difference per 100 mm or 10" diameter  | 600 | | | 15.0 | 10.0 |
| | 750 | 0.13 | 0.09 | | |
| | 900 | | | 10.0 | 7.0 |
| | 1200 | | | 8.0 | 5.0 |
| | 1500 | 0.07 | 0.05 | | |
| | 1800 | | | 5.0 | 3.0 |
| | 3000 | 0.04 | 0.03 | | |
| | 3600 | | | 3.0 | 2.0 |
| | 6000 | 0.03 | 0.02 | | |
| | 7200 | | | 2.0 | 1.0 |

Tolerance table 📶 mm 🔋

Press ENTER to disable tolerances.

Diameter: 100 mm Enabled




| RPM | ■ ■ ■ ■ Acceptable | ■ ■ ■ ■ Excellent |
|-------------------------------------------|----------------------------------------------------------------------------------------------------------------------------------------------------------------|---------------------------------------------------------------------------------------------------------------------------------------------------------------|
| 750 | Gap: 0.13 Offset: 0.19 | Gap: 0.09 Offset: 0.09 |
| ● 1500 | Gap: 0.07 Offset: 0.09 | Gap: 0.05 Offset: 0.06 |
| 3000 | Gap: 0.04 Offset: 0.06 | Gap: 0.03 Offset: 0.03 |
| 6000 | Gap: 0.03 Offset: 0.03 | Gap: 0.02 Offset: 0.02 |

Save File

Save machines


200
Files

- Dimensions
- Measurements
- Diagnosis
- Settings







Print Report – Save PDF Report to USB stick

File management



Save PDF to USB drive

- Copy PDF to PC to print
- Save to PDF on PC for history



Also print to printer
- Need printer USB cable

Document work with PDF Reports


| Fluke 830 LASER ALIGNMENT TOOL Report | | | |
|------------------------------------------------------------------------|------------------------------------------|-------------|--------|
| File info | | | |
| Filename: | sample | | |
| Created: | 20-March-2014, 12:38:51 | | |
| Measured: | 20-March-2014, 19:02:42 | | |
| Comment: | | | |
| Machine dimensions | | | |
| | Value: | Unit: | |
| Static | | | |
| Coupling | Coupling diameter: | 10.000 | [inch] |
| | Distance from sensor to prism | 45.000 | [inch] |
| | Distance from sensor to coupling centre: | 22.500 | [inch] |
| | Distance to right machine: | 65.000 | [inch] |
| | RPM: | 1800 | RPM |
| Movable | | | |
| | Distance from 1 to 2 Feet: | 75.250 | [inch] |
| Dimensions [inch] | | | |
| | | | |
| Machine coupling diagnose | | | |
| | Actual: | Value: | Unit: |
| | Results of Sweep Measurement | | |
| Vertical: | | | |
| | Gap | -0.7 | [mils] |
| | Offset | -2.2 | [mils] |
| | Vertical tolerance: | | |
| Horizontal: | | | |
| | Gap | -0.4 | [mils] |
| | Offset | +1.3 | [mils] |
| | Horizontal tolerance: | | |
| Machine foot corrections | | | |
| Static | | | |
| Movable | Vertical: | Horizontal: | Unit: |
| Foot 1 | -2.4 | -3.7 | [mils] |
| Foot 2 | -7.7 | -6.5 | [mils] |
| Printed: 28-March-2014, 13:29:58 Ver.: 1.00 S/N: 65431612 Page: 1 of 2 | | | |

| Fluke 830: Fluke 830 LASER ALIGNMENT TOOL Report | | | |
|------------------------------------------------------------------------|--------|--------|------|
| Graphical machine diagnose [mils] | | | |
| Vertical | | | |
| Gap | -0.7 | | |
| Offset | -2.2 | -2.4 | -7.7 |
| Horizontal | | | |
| Gap | -0.4 | | |
| Offset | +1.3 | -3.7 | -6.5 |
| Tolerances | | | |
| Coupling | Value: | Unit: | |
| RPM | 1800 | | |
| Excellent: | | | |
| Gap | 4.6 | [mils] | |
| Offset | 2.1 | [mils] | |
| Acceptable: | | | |
| Gap | 6.4 | [mils] | |
| Offset | 3.3 | [mils] | |
| Soft foot measurements [mils] | | | |
| Static: No soft foot values taken | | | |
| Movable: No soft foot values taken | | | |
| Printed: 28-March-2014, 13:29:58 Ver.: 1.00 S/N: 65431612 Page: 2 of 2 | | | |


Data protection





1. Press Menu and choose device settings
2. Change Resume Setting to Always Resume
3. It allows you to open the last used measurement file



Extend Detector Range






- Gross misalignment of shafts or angular misalignment over large distances can cause the laser beam to miss the detector surface during measurement.
- When this happens, 'Laser End' appears on the display screen and the 'Extend' function can be used.
- Shaft should be rotated backwards until the laser beam re-enters the measurement range and then the Extend function can be started





Measurement options – Extend


- Extend interrupts measurement and switches to the beam adjustment screen



- Current beam position is automatically recorded and taken as starting point for range extension. Center the laser dot as restart point for next measurement,
- Continue measurement as before, rotating shafts and pressing ENTER to take measurements at the available positions.
- Program includes displacement of beam readjustment in its alignment calculations





Switch Machine Set-up




1. Select Left machine or Right Machine
Moveable (motor) on Right is preferred unless obstruction makes switching necessary

2. Select stationary or movable or the flange position







Measurement Options – Clock Mode




Clock mode is used for




- Uncoupled shafts
- Nonrotatable shafts
- Vertical foot-mounted



Measurement options – Vertical Machines



The circular housing is numbered clockwise looking down the shaft, starting at 0 followed by the clock positions 1:30, 3:00, 4:30, 6:00, 7:30, 9:00 and 10:30.





Take from 3 up to 8 measurement positions

Shim corrections are numbered to correspond with bolt positions

Measurement options – Averaging







Averaging

- It may be necessary to increase number of measurements to attain a desired accuracy
- Particular cases include applications with increased machinery vibration
- Increased averaging improves accuracy when measuring sleeve bearings, white metal bearings and journal bearings





System Settings – Device, Regional, Default


FLUKE®



Sensor selection & Laser beam adjustment



Highlight 'Scan' and press ENTER to scan wireless modules within nearby.



Once detected, the module is automatically connected and communication established between the sensor and the 830.

The serial number of the wireless module in use is displayed on the screen during measurement.

Now proceed with laser beam adjustment



Laser beam adjustment

Adjust prism until GREEN sensor LED lights and 830's right LED turns blue

- Sensor has a red and a green LED to indicate beam adjustment condition
 - 830 simultaneously monitors alignment with the right LED
- When reflected beam fails to strike detector surface, right LED on 830 turns red and sensor red LED blinks
- Message 'Laser OFF' appears on display screen
 - Adjust reflected beam using prism metal thumbwheel and yellow adjustment knob
 - As reflected beam strikes edge of detector, right LED on 830 turns orange with the red sensor LED blinks quickly.
 - Message 'Laser End' appears on the display screen.

Note

*Make sure that prism and sensor lens are clean.
Use a soft lint-free cloth.
A lens cleaning cloth is supplied.*





Laser beam adjustment

Center beam such that 830's right LED turns **blue (green?)**



Adjust laser beam until laser dot is positioned in green square in center of detector

- Horizontal adjustment with yellow prism knob
- Vertical adjustment with the side metal thumbwheel

Right LED on 830 turns **blue**





RED sensor LED blinks quickly while GREEN is OFF
830's RIGHT LED turns RED



Both sensor LEDs blink quickly and alternately
830's RIGHT LED turns ORANGE

Laser beam adjustment

Center beam such that 830's right LED turns **blue (green?)**




GREEN sensor LED blinks slowly
830's RIGHT LED turns **GREEN (BLUE?)**



Notes

- Beam does not have to be exactly at center of crosshair - will not affect measurement accuracy. However, maximum range for measurement is available when beam is well centered.
- Once centered, sensor and prism must not be touched - any movement during measurement will be interpreted as misalignment. Components may be moved when extending measurement range.

Red arrow on yellow knob assists user by indicating which way knob to be turned. Closer beam comes to being centered, the smaller this arrow becomes. When laser beam is inside center square, GREEN sensor LED lights constantly.






Appendix

- ✓ Sensor Cable – wireless not available
- ✓ Update – 830 and sensor firmware
- ✓ Technical Specifications
- ✓ Optional – magnetic brackets and shims
- ✓ Service & Calibration


Appendix - Using Sensor Cable

If you need to use the sensor cable (due to flat batteries in the wireless module)





Appendix – Update 830 firmware




Firmware update is carried out using the memory stick and the 'short' USB cable. The actual update does not require a PC.



Note
Before proceeding with the update ensure that the indicated nominal capacity of the battery is greater than 50%. If this is not the case, recharge the battery to full capacity first.




Appendix – Update 830 firmware



Appendix – Update sensor firmware

If a sensor with an older firmware version is connected to the Product, a hint indicating that sensor firmware requires updating appears on display



830 Laser Alignment Tool technical data

FLUKE®

Product

| | |
|--------------------------|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| CPU | Intel XScale PXA270 running at 312 MHz |
| Memory | 64 MB RAM, 32 MB Flash |
| Display | Type: TFT, transmissive (sunlight-readable), 65 535 colours, backlit LED Integrated light sensor for automated adjustment of the brightness to the display according to the lighting conditions hence extending battery life Resolution: 320 x 240 Pixel Dimensions: 3.5 inch [8.9 cm] diagonal Keyboard elements: SETUP, MEASURE, DIAGNOSE, MENU, CLEAR, ENTER, BACK keys, Navigation cursor cross, alphanumeric keyboard and on/off button |
| LED indicators | Multicolour LED for laser status and alignment condition Multicolour LED for battery status |
| Power supply | Integrated Lithium-ion polymer rechargeable battery: 7.4 V / 2.6 Ah with typical operating time of 17 hours (based upon an operating cycle of 33% measurement, 33% computation and 33% 'sleep' mode) |
| External interface | USB host USB device (slave) RS232 (serial) for sensor AC adapter/charger socket |
| Environmental protection | IP 65 (dustproof and water spray resistant), shockproof Relative humidity 10% to 90% |
| Temperature range | Operation: -10°C to 50°C [14°F to 122°F] Storage: -20°C to 60°C [-4°F to 140°F] |
| Altitude | 2000 m [6500 ft] |
| Dimensions | Approx. 220 x 165 x 45 mm [8.7" x 6.5" x 1.8"] |
| Weight | 742 g [1.64 lb] |

830 Laser Alignment Tool technical data

FLUKE®

Sensor

Particulars

Measurement principle: Coaxial, reflected laser beam
Environmental protection: IP 67 (submersible, dustproof)
Ambient light protection: yes
Storage temperature: -20°C to 80°C [-4°F to 176°F]
Operating temperature: 0°C to 55°C [32°F to 131°F]
Dimensions: approx. 107 x 70 x 49 mm [4 1/4" x 2 3/4" x 2"]
Weight: approx. 177 g [6 1/2 oz.]

Laser

Type: Ga-Al-As semiconductor laser
Wavelength (typical) 675 nm (red, visible)
Beam power: < 1 mW

Detector

Measurement area: unlimited, dynamically extendible
Resolution: 1 µm
Accuracy (avg): > 98%

Inclinometer

Measurement range: 0° to 360°
Resolution: <1°

Prism

Particulars

Type: 90° roof prism
Accuracy (avg): > 99%
Environmental protection: IP 67 (submersible, dustproof)
Storage temperature: -20°C to 80°C [-4°F to 176°F]
Operating temperature: -20°C to 60°C [-4°F to 140°F]
Dimensions: approx. 100 x 41 x 35 mm [4" x 1 5/8" x 1 3/8"]
Weight: approx. 65 g [2 1/2 oz.]

830 Laser Alignment Tool technical data

FLUKE®

Wireless module

Particulars

Class 1 connectivity, transmitting power 100 mW
Transmission distance: 10 m [33 ft.]
Complies with FCC rules part 15.247
LED indicators: 1 LED for Bluetooth communication,
3 green LEDs for battery status
Power supply: Batteries 2 x 1.5 V IEC LR6 ("AA")
Operating time: 14 hours typical use (based upon an operating cycle
of 50% measurement, 50% standby)
Storage temperature: -20°C to 60°C [-4°F to 140°F]
Operating temperature: -10°C to 50°C [14°F to 122°F]
Environmental protection: IP 65 (dustproof and water spray resistant),
shockproof
Dimensions: Approx. 81 x 41 x 34 mm [3 1/8" x 1 11/16" x 1 5/16"]
Weight: Approx. 133 g [4.7 oz.] including batteries and cable

Safety

Electrical

IEC 61010-1

Battery

IEC 62133

Laser

IEC 60825-1, 21 CFR 1040.10, .11 with Laser Notice 50

Electromagnetic Environment

Particulars

IEC 61326-1: Basic

Radio Frequency Emissions

Particulars

IEC CISPR 11: Group 1, Class A.

Group 1 have intentionally generated and/or use conductively coupled radio-frequency energy which is necessary for the internal functioning of the equipment itself.

Class A equipment is suitable for use in non-domestic locations and/or directly connected to a low-voltage power supply network.

Mounting sensor and laser

| | |
|-----------------------------------------------------------------------------------------------------------|---------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| How do I position myself in front of the machines? | The graphic in the 'Set-up' screen shows the sensor on the left machine and the prism on the right machine which is the MTBM (usually the motor). |
| Where can I mount the chain type bracket? | The chain type bracket may be mounted either directly on the shaft or on the coupling. |
| Is there a minimum distance required between the sensor and the prism? | The components must never touch one another during rotation of the shafts. |
| Is there a maximum distance between the sensor and the prism? | The recommended maximum distance is ca. 5 m (197 in.) |
| Do surfaces of shafts and couplings have an influence on the results? | During the shaft alignment procedure, the shafts (as well as the couplings) are rotated, and therefore, any uneven or rough surfaces have no bearing on the result. |
| Does the distance between the sensor and the reflector play a role in the accuracy of the results? | The larger the separation distance between the sensor and the laser the higher (better) the accuracy. |
| Does the physical position of the sensor and laser on the support posts influence the results? | The sensor and laser may be mounted at any height on the support posts. Mount as low as possible but high enough for beam to clear coupling flange. |

Entering dimensions

| | |
|-------------------------------------------------------------------------------------------|---------------------------------------------------------------------------------------------------------|
| How exact must the inputted dimensions be? | Readings within +/- 2 mm (+/- 1/16 in.) taken with the standard tape measure are sufficient. |
| Where is the coupling plane? | The coupling plane is the point of power transmission (this could be at the elastomer or disc location) |
| How should foot dimensions be entered when measuring large non-symmetric machines? | The dimensions should be taken from the center of the foot bolts. |

Initializing sensor and laser

| | |
|---------------------------------------------------------------------------------|--------------------------------------------------------------------------------------------------------------------|
| Sensor initialization has failed. | Wireless module has not been turned on/connected to the sensor, or the Wireless module batteries have no capacity. |
| The laser beam cannot be detected on the laser dust cap. | Lighting condition of the surroundings is extremely bright. |
| Are any extra safety precautions necessary when working with the laser? | Do not look directly into the laser beam at any time. |
| The laser beam does not strike the sensor. | The yellow reflector knob has been misadjusted or there is a considerable angular misalignment. |
| The sensor cannot be detected by the computer. | The Wireless module has not been assigned within the computer. |
| The laser cannot be correctly adjusted or is not detected by the sensor. | The powerful source of light out powers the sensor detector. |

Measurement (turn shafts)

Which causes can influence the measurement and lead to poor measurement repeatability?

Note:

Tolerance table gap values (included within slide 37) are based on actual coupling gap (gap tolerance limits automatically updated based on entered diameter in Setup screen).

The printed tolerance table gap values included within the instructional manual are based on 'fixed' gap values for set for 100mm or 10 in. diameter (referenced within slide 65).

- Loosely mounted bracket frame
- Support posts mounted on bracket frame loosely
- Loose mounting of the sensor and laser on the support posts
- Loose machine anchor bolts
- Unstable or damaged machine foundation
- Sensor and laser brush the shafts or strike the machine foundation during shaft rotation
- Sensor and laser touched during shaft rotation
- Restoring force of tight couplings due to gross misalignment
- Shafts initially rotated in a direction opposite to the normal direction of operation, and then changed to during measurement to the normal direction of operation
- Friction bearing machines with active oil pump
- Temperature effects within the machines (coupling heating up or heaters)
- External vibration from other rotating machinery

Results and Move

| | |
|----------------------------------------------------------------------------|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| What is V – vertical and H – horizontal? | V is the side view (height) and H is the plan view of the machine combination. |
| On which coupling diameter are the coupling gap values based? | Gap values are based on the coupling diameter entered in the Set-up screen. |
| Is the analysis of the results influenced by the coupling diameter? | The resulting gap values are recalculated for a coupling diameter of 100 mm (10 in.), and are then comparable with the internal table values. |
| How are the foot corrections to be assessed? | The values show the position of the machine with respect to the reference machine. Positive values indicate that the machine is lower or closer to the viewer. |
| How are the arrows and the machine feet to be interpreted? | The arrows indicate the foot correction to be made. If arrow faces upwards, machines required adding shims. If arrows are directed away from the viewer, the machine is to be moved away from viewer. |

Speedy mounting for shaft alignment products



Compact magnetic bracket

For instant mounting onto any ferromagnetic surface

- Instant mounting
- Fits onto any ferromagnetic surface
- Extremely stable, but simple to adjust


Instant mounting on any ferromagnetic surface: just place the compact magnetic brackets onto coupling flanges or shaft faces and you're all set! Four powerful magnets hold sensors firmly in place for measurement – even on narrow coupling flanges – yet allowing extremely easy and flexible adjustment.

Precision Shims – for precision alignment

FLUKE®

PERMABLOC

Stainless steel precut shims –
The alignment time-saver




Designed to speed up the alignment job when even minutes of downtime count

- Bur-free for higher accuracy in machinery alignment
- Several machine foot sizes and thicknesses
- Corrosion-resistant high-quality stainless steel
- Time-saving permanent thickness / dimension marking
- No 'leaf spring' effect from stacked shims: only 3 shims are enough!
- Perfectly flat for stable, consistent machine support
- Perforated tab for easier positioning and removal



Alignment tool



Single Laser
sensor - prism

Inclinometer station



Calibration station

